

DPM 2500

DOUGLAS AIRCRAFT COMPANY

3855 Lakewood Boulevard Long Beach, California 90846

Sodium Lauryl Sulfate

October 21, 1977

C1-726-269

SFS

Emery Industries, Inc.
5568 East 61st Street
Los Angeles, California 90040

Gentlemen:

This facility must, on occasion, reship your product, Sodium Lauryl Sulfate, EM/SAL 6464

In order to insure our compliance with the Hazardous Materials Regulations of the Department of Transportation, Title 49, Code of Federal Regulations, it is requested this office be advised as to whether or not your product is a regulated or restricted article for shipment by surface or air modes of transport.

Should the product be regulated, please indicate:

1. DOT Proper Shipping Name per Section 172.101, 49 CFR.
2. DOT Hazard Classification per Section 172.101, 49 CFR.
3. Flash Point and Closed Cup method per Section 173.115, 49 CFR.
4. IATA Article Number.

It is further requested this office be furnished a current copy of the Occupational Safety and Health Administration (OSHA) Material Safety Data Sheet if available.

Your cooperation and prompt reply will be appreciated.

Very truly yours,

M. J. Veneroso

M. J. Veneroso, Dept. C1-726 (52-11)
Materials Handling & Packaging Engineering
Douglas Aircraft Company

WTJ:rc

11-7-77

The above listed product is non hazardous.

MCDONNELL DOUGLAS

CORPORATION

Don A. Iiams
Don A. Iiams, Traffic Mgr.

"Cleaning Compound Liquid"
per Ralph Cooke, Emery Ind. @ 5-685-5664

BOE-C6-0204218